












Wednesday, 22/10/2008 4:07:41 PM
 User: Julie Dawson

Process Sheet

Customer : CC-DAR01 Dart Aerospace Ltd.	Drawing Name : SEAT SUPPORT ASSEMBLY, LH
Job Number : 42864	
Estimate Number : 13328	
P.O. Number :	Part Number : D3784043
This Issue : 22/10/2008 S.O. No. :	Drawing Number : D3784 REVB
Prsht Rev. : NC	Project Number :
First Issue : / / Type : SMALL /MED FAB	Drawing Revision : B
Previous Run : 42863	Material :
Written By :	Due Date : 07/11/2008 Qty: 2 Um: Each
Checked & Approved By : <u>JD 08.10.22</u>	
Comment : Est Rev:A 08-05-19 new issue DD verified by:ec Est Rev:B 08-07-18 revB as per dwg DD verified by:EC	
Additional Product	
Job Number: 	
Seq. #:	Machine Or Operation:
Description :	
1.0	PACKAGING 1
	PACKAGING RESOURCE #1
	
	
Comment: PACKAGING RESOURCE #1 Pick Packing Kit	
2.0	D3763043
	End Fitting Assembly, LH
	
	
Comment: Qty.: 1.0000 Each(s)/Unit Total : 2.0000 Each(s) End Fitting Assembly, LH batch: <u>B42954</u> <u>FF 09/02/24</u> (2)	
3.0	D37701
	Tube
	
	
Comment: Qty.: 1.0000 Each(s)/Unit Total : 2.0000 Each(s) Tube batch: <u>B42879</u> <u>FF 09/02/24</u> (2)	
4.0	D37703
	Tube
	
	
Comment: Qty.: 1.0000 Each(s)/Unit Total : 2.0000 Each(s) Tube batch: <u>B42963</u> <u>FF 09/02/24</u> (2)	
5.0	D3763041
	End Fitting Assembly
	
	
Comment: Qty.: 2.0000 Each(s)/Unit Total : 4.0000 Each(s) End Fitting Assembly batch: <u>B42949 x 2 / B42948 / 2</u> <u>FF 09/02/24</u> (2)	

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 22/10/2008 4:07:41 PM
User: Julie Dawson

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: SEAT SUPPORT ASSEMBLY, LH

Job Number: 42864

Part Number: D3784043

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

AN960JD10L

Washer



Comment: Qty.: 4.0000 Each(s)/Unit Total : 8.0000 Each(s)

Washer

batch: 17109632

(or NAS1149Do332J) batch: _____

FF 09/02/24 (2)

7.0

MS21042L3

Nut



Comment: Qty.: 4.0000 Each(s)/Unit Total : 8.0000 Each(s)

Nut

batch: 17109798

FF 09/02/24 (2)

8.0

AN52510R20

Screw



Comment: Qty.: 4.0000 Each(s)/Unit Total : 8.0000 Each(s)

Screw

batch: 17109752

FF 09/02/24 (2)

9.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

1-assemble as per dwg D3784

****Note 8: Hole "A" is located 5" from the end of D3770-3 tube and must be oriented up****

****Note 8: Hole "B" is located 5" from the end of D3770-1 tube and must be oriented AFT****

FF 09/02/24 (2)

10.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

S 09/02/24 (0244)

11.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify with Dart part # and batch # using a fine point permanent marker on inside of part and Stock

Location: _____

PC 9/14/25

12.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

09/02/25

Job Completion



h 29.02.25

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

8 7 6 5 4 3 2 1

D


C

B

A

ITEM NO.	PART NUMBER	DESCRIPTION	QTY. (-043)
1	D3763-043	END FITTING ASSY, LH	1
2	D3770-1	TUBE	1
3	D3770-3	TUBE	1
4	D3763-041	END FITTING ASSY	2
5	NAS1149D0332J	WASHER (AN960JD10L)	4
6	MS21042L3	NUT	4
7	AN525-10R20	SCREW	4

B
B
B



D3784-043 SEAT SUPPORT ASSY, LH


NOTES:

- 1) MATERIAL: N/A
- 2) FINISH: N/A
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: N/A
- 7) WEIGHT: 0.78 lbs

8 7 6 5 4 3 2 1

DESIGN	HS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
DRAWN	HS	
CHECKED	PA	DRAWING NO. D3784
MFG. APPR.	NO	REV. B SHEET 2 OF 5
APPROVED	NO	TITLE SEAT SUPPORT ASSEMBLY
DE APPR.	NO	SCALE NTS
DATE	08.06.23	COPYRIGHT © 2008 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 212864



SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 42864

DESIGN	HS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	HS		
CHECKED	<i>[Signature]</i>	DRAWING NO. D3784	REV. B
MFG. APPR.	<i>[Signature]</i>	SHEET 3 OF 5	
APPROVED	<i>[Signature]</i>	TITLE	SCALE
DE APPR.	<i>[Signature]</i>	SEAT SUPPORT ASSEMBLY	NTS
DATE	08.06.23	<small>COPYRIGHT © 2008 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.</small>	